




Instruction Manual


ON-FLOOR SIT-STAND WORKSTATION



WS101



► SCREW PACKAGE



A M6x40(x4)



B M5x12(x10)




C M6x11(x4)



D S=5mm(x1)


► PARTS INCLUDED

①




(x1)

②




(x1)

③



(x1)

④



(x1)


► INSTALLATION

①

S=5mm
D

M6x40
A

③




②

D
S=5mm

M5x12
B


S=5mm
D

M5x12
B




► INSTALLATION


3



4



5



6

